

## SUSSEX VILLAGE HALL EXISTING CONDITIONS STUDY

---

This evaluation was conducted by a team of professionals from Plunkett Raysich Architects and Mortenson Construction. The team visually reviewed the building, researched available building plans, and reviewed current building codes as necessary to gather information. The building evaluation was non-destructive. Comments made are based on exposed, observed conditions.

The Sussex Village Hall was originally constructed as a public grade school in 1922. The school facility was renovated in 1961. The school was closed in 1979. In 1989, the facility was renovated and became the Village Hall.

Exterior walls of the original building are load bearing masonry construction with a brick and stone exterior veneer. Remaining original interior partitions appear to also be load bearing masonry construction. Masonry walls generally are furred out with gypsum wall board applied. It is believed no insulation exists in the exterior wall assembly.

The floor structural system could only be partially observed in the lower level mechanical room. Its composition was observed to be of terra cotta blocks, possibly "Docks Blocks." Drawings from the 1961 renovation indicate wood frame construction with wood plank subflooring.

Roofing composition appears to a fully adhered EPDM membrane on wood decking on a tapered wood truss framing system. Drainage is through a metal gutter and downspout system on the north side of the building.

The summary provided below and in the following photographs identifies items observed by Plunkett Raysich Architects during a site visit conducted on Wednesday, April 28, 2010.

### I. SITE

#### A. Parking

1. The existing parking lot lies to the north and west of the building and is shared with the Sussex Library.
2. Pavement appeared to be in generally good condition and adequately drained. Sealing and restriping should be performed in the near future. Refer to photo 2.0.1.

#### B. Adequate Parking / Observed Traffic Flow

1. Parking counts appear to be adequate for Village Hall purposes but it has been reported parking is inadequate at times when traffic at the library is high.

#### C. Accessibility

1. A route was observed from the parking lot to the east side of the building where a separate, dedicated entrance is located to provide access to the elevator. The route appears to be too steep to meet current

SUSSEX VILLAGE HALL  
EXISTING CONDITIONS STUDY

---

ramp guidelines and, strictly speaking, this separate entrance is not compliant with the Americans With Disabilities Act.

D. Guardrails

1. Picket spacing was observed to be greater than current code allowance. Refer to photo 2.0.2.
2. Guardrail baluster pockets in concrete walls were observed to be generally open and unsealed. All pockets should be cleaned, steel guardrails cleaned and painted and pockets filled with backer rod and sealant. Refer to photo 2.0.3.

E. Drainage

1. Ponding water at the elevator vestibule is a continuing problem. A site drain should be added to remedy this.

F. Handrails

1. An intermediate handrail at the front entry stair is likely required to comply with building egress code. Code requires all portions of the stairway width required for egress capacity be within 30 inches of a handrail. Refer to photo 2.0.4.

**II. BUILDING – EXTERIOR**

A. Masonry Walls

1. Masonry is generally split face limestone at the base of the building and standard brick above. The 1989 vestibule consists of exposed cast concrete at the base and split face CMU above.
2. Multiple past tuck-point projects were observed at both brick and stone areas. The blending of mortar color was poorly done. Refer to photo 2.0.5.
3. Window lintels appear to be sound but need to be cleaned and repainted. Refer to photo 2.0.6.
4. Mortar at stone base was observed to be beginning to spall in places. All masonry faces should be tuck pointed. Refer to photo 2.0.7.

B. Flashing / Copings

1. Flashing is very limited in the original building. Existing window heads appear to have weep holes but no flashing. Refer to photo 2.0.6.
2. Copings at the parapet appear to be in good condition. Refer to photos 2.0.8 and 2.0.9.

C. 1989 Entry Vestibule Addition

1. Water penetration was observed in the lower level storage room beneath the entry vestibule. The Village Building Inspector noted that water stops were not installed between the foundation walls and the slab above. Refer to photo 2.0.10.

SUSSEX VILLAGE HALL  
EXISTING CONDITIONS STUDY

---

2. Water damage was observed at the junction of the storefront system and the masonry wall at the north side of the vestibule. Refer to photo 2.0.11.
3. Water damage was observed at both sides of the vestibule where the metal roof meets the CMU wall. Refer to photos 2.0.12 and 2.0.13.

D. Doors and Windows

1. Doors and windows were replaced during the 1989 renovation and appear to be in generally satisfactory condition. Window systems consist of insulated glass in an aluminum storefront frame.
2. The lower level courtyard exterior door (adjacent to the meeting room) is showing signs of corroding at the threshold and the base of the frame. Refer to photo 2.0.14.

- E. Light fixtures at lower courtyard entrance are not exterior rated fixtures and need to be replaced. Refer to photo 2.0.15.

**III. BUILDING – ROOF**

A. Main Roof (1922 Building)

1. The roof appears to now be in generally good condition. The building maintenance director indicated that limited to no maintenance has been performed on the membrane system since its installation in 1989.
2. The roofing system over the main, original building is a Carlisle EPDM fully adhered membrane roof system. Refer to photo 2.0.16.
3. Membrane seams and flashing are beginning to peel back in numerous locations. These are should be repaired as soon as possible to avoid water penetration and further damage. Refer to photos 2.0.17 and 2.0.18.
4. Water penetration was observed at the roof scuttle. Refer to photo 2.0.19.
5. Water appears to be ponding at the east side of the north gable. The insulation below the membrane felt soft when walked on. This are should be monitored for signs of water intrusion. Refer to photo 2.0.20.

B. Attic

1. The attic space is insulated with blown in mineral wool insulation of varying depth. A vapor barrier was not observed. Refer to photo 2.0.21.
2. Ventilation appears to be provided by a wooden louver unit at the west face of building. The unit is badly deteriorated and must be replaced. Refer to photo 2.0.22.

C. Vestibule Roof (1989 Addition)

1. Gutters on the standing seam metal roof at the 1989 vestibule addition appear to be inadequately sized and have been damaged by ice. Refer to photos 2.0.23 and 2.0.24.
2. A snow and ice retention system should be installed.

SUSSEX VILLAGE HALL  
EXISTING CONDITIONS STUDY

---

**IV. BUILDING – INTERIOR**

**A. Water Damage**

1. Some evidence of water intrusion was apparent around window frames on the second floor. Refer to photo 2.0.25.
2. Some water stained ceiling tiles were observed.

**B. Electrical Panel Clearance**

1. Code requires 3'-0" of clear space in front of all electrical panels. The roof access ladder intrudes on this clearance currently. A retractable ladder should be installed to remedy this. Refer to photo 2.0.26.

**C. Toilet Rooms**

1. All toilet rooms are worn and should be upgraded to comply with current accessibility requirements.
2. Toilet partitions in the lower level toilet rooms are corroding and need to be replaced. Refer to photo 2.0.27.

**D. Stair Handrails & Guards**

1. Handrails appeared to be code compliant and do not require work at this time.

**E. Finishes**

1. Carpet throughout the facility is worn and separating at the seams. All carpet should be replaced. Refer to photos 2.0.28 and 2.0.29.
2. Resilient base was observed throughout the facility. It is in varying states of condition but should all be replaced as part of a larger interior finishes upgrade.
3. Interior walls are primarily painted and in generally good condition. Some general maintenance such as patching and touching up is required. Paint around several window openings was observed to be failing. It was not obvious that this is due to water infiltration but it should be monitored and repaired. Refer to photo 2.0.30.
4. Walls in the former Police area office have vinyl wall covering that is in poor condition. All wall surfaces should be stripped, cleaned and refinished.

**F. Ceilings**

1. Ceiling tile through is beginning to sag. All tile and grid should be replaced. Refer to photo 2.0.31.
2. Light levels should be reviewed for adequacy. Consider replacing older florescent fixtures with more efficient modern units.
3. Outdated incandescent track lighting in cove ceilings should be replaced with more efficient units.

**G. A/V Systems**

SUSSEX VILLAGE HALL  
EXISTING CONDITIONS STUDY

---

1. Video systems for broadcast of Village proceedings in the meeting room have been added since the building was converted to its present use. Cable and other hardware are exposed on walls and floors. A redeveloped public meeting room should be considered that properly accommodates current broadcast and recording technologies including lighting and acoustics. Refer to photos 2.0.32 and 2.0.33.

**V. BUILDING MECHANICAL SYSTEMS**

A. HVAC System

1. Building mechanical systems were replaced during the 1989 renovation project.
2. During the site walk through, the roof top mechanical unit was observed to be malfunctioning. It appeared the heating unit was not igniting properly.

B. Elevator

1. The elevator has been reported to overheat and stop operating when used frequently. A temporary workaround has been derived by the Village to restore service but a permanent fix should be implemented.
2. No ventilation is present in the elevator machine room.

**VI. BUILDING – ACCESSIBILITY**


- A. All areas of the building appear to be accessible; however, accessible circulation is sometimes separated by significant distances from the general circulation. An elevator has been added to the east side of the building. Routes are circuitous but present.
- B. Accessible access to the main public lobby and reception desk is extremely poor and requires guests to travel a significantly greater distance to a separate entrance and use an elevator that takes them to the back office corridor behind the Building Inspection Department and the Reception Desk. Additionally, this open access this arrangement requires may constitute a building security risk.
- C. The number of accessible public entrances does not satisfy the code required minimum of 60%. Only one entrance is currently accessible.
- D. Toilet rooms have been upgraded with some accessible elements but the facility does not currently have a completely accessible toilet room. All toilet facilities should be brought up to code requirements.
- E. Door hardware is not compliant with current accessibility requirements. All door handles need to be of a lever type and located between 34” and 48” above finished floor elevation.

SUSSEX VILLAGE HALL  
EXISTING CONDITIONS STUDY


---



2.0.1 Existing parking lot




2.0.2 Picket spacing too large




2.0.3 Baluster pocket open



2.0.4 Intermediate handrail required




2.0.5 Multiple tuck point projects




2.0.6 Window lintels need paint

SUSSEX VILLAGE HALL  
EXISTING CONDITIONS STUDY


---




2.0.7 Spalling mortar



2.0.8 Parapet coping



2.0.9 Parapet coping



2.0.10 Water penetration beneath vestibule



2.0.11 Water damage in vestibule




2.0.12 Water damage in vestibule

SUSSEX VILLAGE HALL  
EXISTING CONDITIONS STUDY


---




2.0.13 Water damage in vestibule




2.0.14 Deterioration at threshold




2.0.15 Wall sconces need to be replaced



2.0.16 Carlisle roof label




2.0.17 Peeling roof membrane




2.0.18 Peeling roof membrane

SUSSEX VILLAGE HALL  
EXISTING CONDITIONS STUDY

---



2.0.19 Water penetration at scuttle




2.0.20 Area of ponding water




2.0.21 Attic insulation



2.0.22 Wood attic vent louver



2.0.23 Vestibule roof



2.0.24 Ice damage to gutters

SUSSEX VILLAGE HALL  
EXISTING CONDITIONS STUDY


---




2.0.25 Apparent water intrusion




2.0.26 Electrical panel clearance




2.0.27 Corrosion on toilet partitions



2.0.28 Worn carpet



2.0.29 Worn carpet




2.0.30 Peeling paint at window

SUSSEX VILLAGE HALL  
EXISTING CONDITIONS STUDY


---



2.0.31 Sagging ceiling tile



2.0.32 Exposed A/V cables



2.0.33 Exposed A/V cables



Sussex Village Hall Maintenance Issues

Version 1a

No.	Project (Work Description)	Priority	No. Units	Unit Measure	Unit Cost	Cost
<b>A Site</b>						
1	Patch, seal and stripe parking lot	C	30,700	SF	\$0.54	\$16,578
2	Replace wall sconce light fixtures at lower courtyard entrance	A	2	LS	\$400.00	\$800
3	Replace guard rails	B	114	LF	\$250.00	\$28,500
4	Install intermediate handrail at entry stair	B	10	LF	\$250.00	\$2,500
5	Provide accessible route to lower level north entrance	C	812	SF	\$5.50	\$4,466
6	Install site drain at elevator vestibule	A	1	LS	\$7,000.00	\$7,000
<b>B Building Exterior</b>						
7	Repair deteriorating roof membrane joints and flashing	A	1,500	SF	\$10.00	\$15,000
8	Tuck point all exterior masonry (stone and brick)	B	8,759	SF	\$10.00	\$87,590
9	Relace threshold and repair door frame at lower level courtyard	B	1	EA	\$500.00	\$500
10	Replace gutters at vestibule roof	A	69	LF	\$13.00	\$897
11	Install snow and ice retention clips on vestibule roof	A	50		\$12.00	\$600
12	Repair roof leaks at vesibule	A	1	LS	\$750.00	\$750
13	Repair leaking roof scuttle	A	1	LS	\$1,500.00	\$1,500
14	Replace attic vent louvers	A	9	SF	\$22.00	\$198



**Sussex Village Hall Maintenance Issues**

Version 1a

No.	Project (Work Description)	Priority	No. Units	Unit Measure	Unit Cost	Cost
<b>C Building Interior</b>						
15	Remove wall covering in former sheriff's department; repair and paint walls	B	765	SF	\$4.00	\$3,060
16	Replace carpets throughout	B	729	SY	\$45.00	\$32,805
17	Replace resilient base throughout	B	INCL. ABOVE			INCL. ABOVE
18	Touchup wall paint	C	2,500	SF	\$0.75	\$1,875
19	Replace ceiling tile and grid	B	4,380	SF	\$4.00	\$17,520
20	Replace outdated light fixtures with more efficient units	B	11,269	SF	\$1.25	\$14,086
21	Renovate toilet rooms to comply with current accessibility requirements	B	440	SF	\$182.00	\$80,080
22	Replace outdated A/V systems in meeting room	C	1	LS	\$25,000.00	\$25,000
23	Replace door hardware w/ accessible pieces	B	26	EA	\$570.00	\$14,820

**Priority Definitions:**

- A Work to be done as soon as possible (1 Year)
- B Work to be done as part of larger project (2 Years)
- C Lower priority at this time (5-10 Years)

**Notes:**

- 1 Items identified after site walk through with Mortenson Construction on 28 April 2010.





Project: **Sussex Village Hall**  
 Project #: 09024

**Total Project Cost Estimate**  
 05/27/2010

Option: A - Minor Renovation  
 Based On: Mortenson Estimate dated 05/27/2010

Cost index: All prices estimated for second quarter 2010.

			Unit	Qty	Cost Range	
	Low	High			Low	High
<b>Building and Site Construction</b>						
A) Village Hall Renovation	-10%	10%	Percentage	\$412,593*	\$	371,334 \$ 453,852
* Per Mortenson Estimate						
<b>Fixtures, Furnishings, Equipment</b>						
A) Furniture	\$ 5,000	\$ 5,000	Lumpsum	1	\$	5,000 \$ 5,000
B) Office Equipment	\$ -	\$ -	-	0	\$	- \$ -
C) Telecommunications System	\$ -	\$ -	-	0	\$	- \$ -
D) Technology systems (Server racks, projectors, etc)	\$ 2,000	\$ 2,000	-	1	\$	2,000 \$ 2,000
				Sub Total	\$	7,000 \$ 7,000
<b>Contingency</b>						
A) Project Contingency	12%				\$	45,000 \$ 55,000
				"Hard Costs" Sub Total	\$	423,334 \$ 515,852
<b>Miscellaneous Expenses &amp; Fees</b>						
A) Fees, State Review, Printing, etc	11.0%		Percentage		\$	47,000 \$ 57,000
B) Moving Expenses	\$ -	\$ -	Occurance	0	\$	- \$ -
C) 12 Month Lease of Temporary Space	\$ -	\$ -	Lumpsum	0	\$	- \$ -
B) Miscellaneous Owner Project Expenses (fund raising, moving, etc.)	1.0%		Percentage		\$	4,000 \$ 5,000
				"Soft Costs" Sub Total	\$	51,000 \$ 62,000
				Range of Total Project Costs	\$	474,334 \$ 577,852
				<b>Probable Total Project Costs</b>	<b>\$</b>	<b>530,000</b>

Note: The "Low" costs are based on based on simple materials and finishes, HVAC and lighting systems that employ older technology, and reuse of old furniture and equipment. The "High" costs represent recent buildings which employ longer lasting construction methods, more diverse finishes, and include sustainable design features such as high efficiency HVAC and lighting, exterior sun shading, interior light shelves, green roof and increased amount of recycled materials.



**VILLAGE OF SUSSEX  
SUSSEX VILLAGE HALL STUDY OPTION A  
SUSSEX, WISCONSIN**

CONSTRUCTION COST ESTIMATE

UNIFORMAT SYSTEM LEVEL 2 SUMMARY  
COST MODEL  
May 27, 2010

UniFormat System Level 2 Breakdown	System Area SF	UM	Cost per Sys. SF	Cost per GSF	Total System Cost
FOUNDATIONS	600 sf		\$15.00	\$0.80	\$9,000
BASEMENT CONSTRUCTION	0 cf		\$0.00	\$0.00	\$0
SUPERSTRUCTURE	0 sf		\$0.00	\$0.00	\$0
EXTERIOR ENCLOSURE	9,674 sf		\$9.10	\$7.81	\$88,040
ROOFING	3,551 sf		\$4.65	\$1.46	\$16,500
INTERIOR CONSTRUCTION	2,500 sf		\$10.94	\$2.43	\$27,355
STAIRS	0 rise		\$0.00	\$0.00	\$0
INTERIOR FINISHES	11,269 sf		\$5.45	\$5.45	\$61,460
CONVEYING	3 stop		\$1,733.33	\$0.46	\$5,200
PLUMBING	11,269 sf		\$5.00	\$5.00	\$56,345
HVAC	11,269 sf		\$2.48	\$2.48	\$28,000
FIRE PROTECTION	0 sf		\$0.00	\$0.00	\$0
ELECTRICAL	11,269 sf		\$2.00	\$2.00	\$22,538
EQUIPMENT	0 sf		\$0.00	\$0.00	\$0
FURNISHINGS	0 sf		\$0.00	\$0.00	\$0
SPECIAL CONSTRUCTION	0 sf		\$0.00	\$0.00	\$0
SELECTIVE BUILDING DEMOLITION	11,264 sf		\$1.51	\$1.51	\$17,030
SITE PREPARATION	0 sf		\$0.00	\$0.00	\$0
SITE IMPROVEMENTS	106,095 sf		\$0.07	\$0.62	\$7,000
SITE CIVIL / MECHANICAL UTILITIES	0 sf		\$0.00	\$0.00	\$0
SITE ELECTRICAL UTILITIES	0 sf		\$0.00	\$0.00	\$0
GENERAL REQUIREMENTS	11,269 sf		\$4.51	\$4.51	\$50,771
<b>UNIFORMAT SYSTEM LEVEL 2 - SUBTOTAL</b>				<b>\$34.54</b>	<b>\$389,239</b>
<b>CONSTRUCTION ESCALATION</b>			<b>0.000%</b>	<b>\$0.00</b>	<b>\$0</b>
<b>SUBTOTAL</b>					<b>\$389,239</b>
<b>INSURANCE / FEE</b>			<b>6.000%</b>	<b>\$2.07</b>	<b>\$23,354</b>
<b>TOTAL CONSTRUCTION COST</b>					<b>\$412,593</b>
<b>COST PER GROSS SQUARE FOOT</b>				<b>\$36.61</b>	<b>\$/GSF</b>
<b>GROSS SQUARE FEET</b>				<b>11,269</b>	<b>GSF</b>



Project: **Sussex Village Hall**  
 Project #: 09024

**Total Project Cost Estimate**  
 05/27/2010

Option: B - Major Renovation and Expansion  
 Based On: Mortenson Estimate dated 05/27/2010

Cost index: All prices estimated for second quarter 2010.

	Cost Range		Unit	Qty	Low	High
	Low	High				
<b>Building and Site Construction</b>						
A) Village Hall Renovation	-5%	8%	Percentage	\$3,483,667*	\$ 3,309,484	\$ 3,762,360
* Per Mortenson Estimate						
<b>Fixtures, Furnishings, Equipment</b>						
A) Furniture	\$250,000	\$300,000	Lumpsum	1	\$ 250,000	\$ 300,000
B) Office Equipment	\$ 30,000	\$ 40,000	Lumpsum	1	\$ 30,000	\$ 40,000
C) Telecommunications System	\$ 30,000	\$ 35,000	Lumpsum	1	\$ 30,000	\$ 35,000
D) Technology systems (Server racks, projectors, etc)	\$ 15,000	\$ 20,000	Lumpsum	1	\$ 15,000	\$ 20,000
				Sub Total	\$ 325,000	\$ 395,000
<b>Contingency</b>						
A) Project Contingency	12%				\$ 436,000	\$ 499,000
				"Hard Costs" Sub Total	\$ 4,070,484	\$ 4,656,360
<b>Miscellaneous Expenses &amp; Fees</b>						
A) Fees, Soil Borings, Survey, State Review, Printing, et	9.0%		Percentage		\$ 366,000	\$ 419,000
B) Moving Expenses	\$ 15,000	\$ 25,000	Occurance	2	\$ 30,000	\$ 50,000
C) 12 Month Lease of Temporary Space	\$ 11	\$ 15	Lumpsum	11,250	\$ 123,750	\$ 168,750
B) Miscellaneous Owner Project Expenses (fund raising, moving, etc.)	1.0%		Percentage		\$ 41,000	\$ 47,000
				"Soft Costs" Sub Total	\$ 560,750	\$ 684,750
				Range of Total Project Costs	\$ 4,631,234	\$ 5,341,110
				<b>Probable Total Project Costs</b>	<b>\$ 4,990,000</b>	

Note: The "Low" costs are based on based on simple materials and finishes, HVAC and lighting systems that employ older technology, and reuse of old furniture and equipment. The "High" costs represent recent buildings which employ longer lasting construction methods, more diverse finishes, and include sustainable design features such as high efficiency HVAC and lighting, exterior sun shading, interior light shelves, green roof and increased amount of recycled materials.



**VILLAGE OF SUSSEX  
SUSSEX VILLAGE HALL STUDY OPTION B  
SUSSEX, WISCONSIN**

**CONSTRUCTION COST ESTIMATE**

UNIFORMAT SYSTEM LEVEL 2 SUMMARY  
COST MODEL  
May 27, 2010

UniFormat System Level 2 Breakdown	System Area SF	UM	Cost per Sys. SF	Cost per GSF	Total System Cost
FOUNDATIONS	6,732 sf		\$15.26	\$5.20	\$102,718
BASEMENT CONSTRUCTION	0 cf		\$0.00	\$0.00	\$0
SUPERSTRUCTURE	8,500 sf		\$26.65	\$11.46	\$226,538
EXTERIOR ENCLOSURE	14,906 sf		\$23.84	\$17.98	\$355,326
ROOFING	6,384 sf		\$11.44	\$3.69	\$73,024
INTERIOR CONSTRUCTION	19,763 sf		\$20.10	\$20.10	\$397,200
STAIRS	43 rise		\$1,000.00	\$2.18	\$43,000
INTERIOR FINISHES	19,763 sf		\$17.11	\$17.11	\$338,155
CONVEYING	3 stop		\$25,000.00	\$3.79	\$75,000
PLUMBING	19,763 sf		\$8.00	\$8.00	\$158,104
HVAC	19,763 sf		\$24.00	\$24.00	\$474,312
FIRE PROTECTION	19,763 sf		\$3.00	\$3.00	\$59,289
ELECTRICAL	19,763 sf		\$18.00	\$18.00	\$355,734
EQUIPMENT	19,763 sf		\$1.26	\$1.26	\$25,000
FURNISHINGS	19,763 sf		\$0.48	\$0.48	\$9,480
SPECIAL CONSTRUCTION	0 sf		\$0.00	\$0.00	\$0
SELECTIVE BUILDING DEMOLITION	11,264 sf		\$14.00	\$7.98	\$157,696
SITE PREPARATION	106,095 sf		\$0.29	\$1.54	\$30,368
SITE IMPROVEMENTS	106,095 sf		\$0.82	\$4.39	\$86,762
SITE CIVIL / MECHANICAL UTILITIES	106,095 sf		\$0.19	\$1.01	\$20,000
SITE ELECTRICAL UTILITIES	0 sf		\$0.00	\$0.00	\$0
GENERAL REQUIREMENTS	19,763 sf		\$15.12	\$15.12	\$298,771
<b>UNIFORMAT SYSTEM LEVEL 2 - SUBTOTAL</b>				\$166.29	\$3,286,478
<b>CONSTRUCTION ESCALATION</b>			0.000%	\$0.00	\$0
<b>SUBTOTAL</b>					\$3,286,478
<b>INSURANCE / FEE</b>			6.000%	\$9.98	\$197,189
<b>TOTAL CONSTRUCTION COST</b>					\$3,483,667
<b>COST PER GROSS SQUARE FOOT</b>				\$176.27	\$/GSF
<b>GROSS SQUARE FEET</b>				19,763	GSF



Project: **Sussex Village Hall**  
 Project #: 09024

**Total Project Cost Estimate**  
 05/27/2010

Option: C - New Stand Alone Two Story Building  
 Based On: Mortenson Estimate dated 05/27/2010

Cost index: All prices estimated for second quarter 2010.

	Cost Range		Unit	Qty	Low	High
	Low	High				
<b>Building and Site Construction</b>						
A) Village Hall Renovation	-5%	5% Percentage		\$4,244,405*	\$ 4,032,185	\$ 4,456,625
(Includes \$200,000 for new parking and other site work to create new outdoor civic areas)						
* Per Mortenson Estimate						
<b>Fixtures, Furnishings, Equipment</b>						
A) Furniture	\$250,000	\$300,000	Lumpsum	1	\$ 250,000	\$ 300,000
B) Office Equipment	\$ 30,000	\$ 40,000	Lumpsum	1	\$ 30,000	\$ 40,000
C) Telecommunications System	\$ 30,000	\$ 35,000	Lumpsum	1	\$ 30,000	\$ 35,000
D) Technology systems (Server racks, projectors, etc)	\$ 15,000	\$ 20,000	Lumpsum	1	\$ 15,000	\$ 20,000
				<b>Sub Total</b>	<b>\$ 325,000</b>	<b>\$ 395,000</b>
<b>Contingency</b>						
A) Project Contingency	10%				\$ 436,000	\$ 485,000
				<b>"Hard Costs" Sub Total</b>	<b>\$ 4,793,185</b>	<b>\$ 5,336,625</b>
<b>Miscellaneous Expenses &amp; Fees</b>						
A) Fees, Soil Borings, Survey, State Review, Printing, et	8.0%	Percentage		\$	383,000	\$ 427,000
B) Moving Expenses	\$ 15,000	\$ 25,000	Occurance	1	\$ 15,000	\$ 25,000
C) 12 Month Lease of Temporary Space	\$ -	\$ -	Lumpsum	0	\$ -	\$ -
B) Miscellaneous Owner Project Expenses (fund raising, moving, etc.)	1.0%	Percentage		\$	48,000	\$ 53,000
				<b>"Soft Costs" Sub Total</b>	<b>\$ 446,000</b>	<b>\$ 505,000</b>
				<b>Range of Total Project Costs</b>	<b>\$ 5,239,185</b>	<b>\$ 5,841,625</b>
				<b>Probable Total Project Costs</b>	<b>\$ 5,550,000</b>	

Note: The "Low" costs are based on based on simple materials and finishes, HVAC and lighting systems that employ older technology, and reuse of old furniture and equipment. The "High" costs represent recent buildings which employ longer lasting construction methods, more diverse finishes, and include sustainable design features such as high efficiency HVAC and lighting, exterior sun shading, interior light shelves, green roof and increased amount of recycled materials and a basement.



**VILLAGE OF SUSSEX  
SUSSEX VILLAGE HALL STUDY OPTION C  
SUSSEX, WISCONSIN**

CONSTRUCTION COST ESTIMATE

UNIFORMAT SYSTEM LEVEL 2 SUMMARY  
COST MODEL  
May 27, 2010

UniFormat System Level 2 Breakdown	System Area SF	UM	Cost per Sys. SF	Cost per GSF	Total System Cost
FOUNDATIONS	19,763 sf		\$15.00	\$15.00	\$296,445
BASEMENT CONSTRUCTION	0 cf		\$0.00	\$0.00	\$0
SUPERSTRUCTURE	19,763 sf		\$12.00	\$12.00	\$237,156
EXTERIOR ENCLOSURE	8,820 sf		\$48.10	\$21.46	\$424,200
ROOFING	19,763 sf		\$8.00	\$8.00	\$158,104
INTERIOR CONSTRUCTION	19,763 sf		\$20.00	\$20.00	\$395,260
STAIRS	0 rise		\$0.00	\$0.00	\$0
INTERIOR FINISHES	19,763 sf		\$15.00	\$15.00	\$296,445
CONVEYING	0 stop		\$0.00	\$0.00	\$0
PLUMBING	19,763 sf		\$8.00	\$8.00	\$158,104
HVAC	19,763 sf		\$20.00	\$20.00	\$395,260
FIRE PROTECTION	19,763 sf		\$3.00	\$3.00	\$59,289
ELECTRICAL	19,763 sf		\$15.00	\$15.00	\$296,445
EQUIPMENT	19,763 sf		\$2.78	\$2.78	\$55,000
FURNISHINGS	19,763 sf		\$0.85	\$0.85	\$16,860
SPECIAL CONSTRUCTION	0 sf		\$0.00	\$0.00	\$0
SELECTIVE BUILDING DEMOLITION	11,269 sf		\$18.00	\$10.26	\$202,842
SITE PREPARATION	106,095 sf		\$1.00	\$5.37	\$106,095
SITE IMPROVEMENTS	106,095 sf		\$4.00	\$21.47	\$424,380
SITE CIVIL / MECHANICAL UTILITIES	106,095 sf		\$1.25	\$6.71	\$132,619
SITE ELECTRICAL UTILITIES	106,095 sf		\$0.50	\$2.68	\$53,048
GENERAL REQUIREMENTS	19,763 sf		\$15.01	\$15.01	\$296,605
<b>UNIFORMAT SYSTEM LEVEL 2 - SUBTOTAL</b>				<b>\$202.61</b>	<b>\$4,004,156</b>
<b>CONSTRUCTION ESCALATION</b>			<b>0.000%</b>	<b>\$0.00</b>	<b>\$0</b>
<b>SUBTOTAL</b>					<b>\$4,004,156</b>
<b>INSURANCE / FEE</b>			<b>6.000%</b>	<b>\$12.16</b>	<b>\$240,249</b>
<b>TOTAL CONSTRUCTION COST</b>					<b>\$4,244,405</b>
<b>COST PER GROSS SQUARE FOOT</b>				<b>\$214.77</b>	<b>\$/GSF</b>
<b>GROSS SQUARE FEET</b>				<b>19,763</b>	<b>GSF</b>